

SPEC SHEET + MEASUREMENTS



Eddie Bauer® Women's WeatherEdge® Plus Insulated Jacket. EB555

Product photo



Built to outlast the elements, this fully seam-sealed technical jacket has exceptional 10K/10K fabric waterproof and breathability ratings thanks to exclusive WeatherEdge Plus technology. Exclusive StormRepel® durable water-repellent (DWR) coating adds extra exterior weather protection. Fully insulated, this jacket also provides long-lasting warmth and comfort when temps drop.

- 100% polyester with durable water-repellent (DWR) coating and TPU film
- Detachable, adjustable hood with locking drawcord
- Full-length exterior storm flap
- Ventilating pit zips
- Princess seams
- Welded front zippered pockets with waterproof zippers
- Interior pocket with elastic to store goggles, hat and bulkier items
- Adjustable tab cuffs with hook and loop closures
- Adjustable locking drawcord hem
- Decoration access pocket
- Contrast heat transfer WeatherEdge Plus logo on left sleeve
- Contrast heat transfer Eddie Bauer logo on right hem

Sketches



front



back

CARE INSTRUCTIONS

Machine wash cold. Delicate cycle. Do not use fabric softener. Tumble dry low. Do not iron. Do not dry clean

SPEC SHEET + MEASUREMENTS



Eddie Bauer® Women's WeatherEdge® Plus Insulated Jacket. EB555

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	29	29 5/8	30 1/4	30 7/8	31 1/2	32 1/8	32 3/4	33 3/8
Bust	20	21	22	23 1/2	25	26 1/2	28 1/2	30 1/2
Size	2	4/6	8/10	12/14	16/18	20/22	24/26	28/30
Sleeve Length	34	34 1/2	35	35 5/8	36 1/4	36 7/8	37 1/4	37 5/8

Body Length at Back: Measured from high point shoulder to finished hem at back.

Bust: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Bust	32-33	34-35	36-37	38-40	41-43	44-46	47-49	50-52
Size	2	4/6	8/10	12/14	16/18	20/22	24/26	28/30

SPEC SHEET + MEASUREMENTS



Eddie Bauer® Women's WeatherEdge® Plus Insulated
Jacket. EB555

HOW TO MEASURE



BUST

Measure under the arm and around
the fullest part of the bust with arms
down, keeping tape horizontal.

COLORS



Black
PMS BLACK
C



Metal Grey
PMS 425 C