

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® SuperPro™ Twill Shirt. S663

Product photo



A heavy hitter in performance, our SuperPro Twill Shirt easily resists wrinkles while releasing stains. Designed for comfort, this versatile shirt functions well in almost any work environment from the office to food service.

- 3.4-ounce, 55/45 cotton/poly
- Button-down collar
- Back shoulder pleats
- Dyed-to-match buttons
- Left chest pocket
- Rounded adjustable cuffs

CARE INSTRUCTIONS

Machine wash warm with like colors. Non-chlorine bleach if needed. Tumble dry low. Remove promptly and hang. Warm iron if needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® SuperPro™ Twill Shirt. S663

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	30	31	32	33	34	35	35 1/2	36
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Neck	17	17	17 1/2	18	19	20	21	22
Pocket Height	5 3/8	5 3/8	5 5/8	5 5/8	5 5/8	5 5/8	5 5/8	5 7/8
Pocket Width	4 5/8	4 5/8	5 1/8	5 1/8	5 1/8	5 1/8	5 1/8	5 5/8
Sleeve Length from Center Back	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Neck: Measured from center of button to center of buttonhole.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SPEC SHEET + MEASUREMENTS


PORT AUTHORITY

Port Authority® SuperPro™ Twill Shirt. S663

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS

							
Black PMS BLACK C	Monument Grey PMS COOL GRAY 9C	Rich Red PMS 207C	Sterling Grey PMS 425 C	True Blue PMS 654C	True Navy PMS 533C	Ultramarine Blue PMS 7455C	White