

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Rain Jacket. J714

Product photo



Designed to shrug off wet conditions, this carbon-reducing C-FREE jacket helps keep you drier and little more sustainable.

- 100% recycled polyester shell and lining
- This product's carbon footprint has been measured and reduced through a combination of preferred materials and investing in carbon offset projects through the ClimeCo Certified Product™ Program
- Fabric waterproof rating: 8000MM
- Fabric breathability rating: 5000G/M²
- Attached, adjustable hood
- Full-length exterior storm flap with hidden snaps
- Hidden zippered pockets
- Adjustable hook and loop tabs at cuffs
- Adjustable locking drawcord at slight drop tail hem
- Port Pocket™ for decoration access
- Water protection method: water-resistant finish, fully seam-sealed

Sketches



front



back

A C-FREE® Product

We start by reducing the product's impact by switching to at least 50% preferred materials. We then measure and reduce the total carbon footprint of each product in the C-FREE program—from cradle-to-grave—through the ClimeCo Certified Product™ Program. This certification purchases third-party, verified carbon offsets through ClimeCo.

CARE INSTRUCTIONS

Machine Wash Cold. Do Not Bleach. Cool Iron If Needed. Do Not Dry Clean.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Rain Jacket. J714

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	26	27	28	29	30	31	31 1/2	32
Chest	19 1/4	20 3/4	22 1/4	23 3/4	25 1/4	26 3/4	28 3/4	30 3/4
Sleeve Length from Center Back	34 3/4	35 1/2	36 1/4	37	37 3/4	38 1/2	39 1/4	40

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Rain Jacket. J714

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS

				
Deep Black PMS BLACK C	Grey Steel	Rich Red PMS 207C	True Navy PMS 533C	True Royal PMS 7687C